



Job Chronicle: J-115248

Location: Hermiston, OR

Date of Work: June 2012

Project: B-3042 - Transformer to re-
pair facility and back

This transformer was in need of repair so HLI was hired to move it from its foundation in Hermiston, Oregon to the repair facility located in Anaheim, CA. The transformer was moved from Oregon to California by rail. The unit was repaired over the next few quarters and ready to be shipped back to its foundation and back into service in June of 2012. The substation was not rail served so the spur nearest the substation was the rail destination. Once the rail car arrived at the designated spur, the transformer was removed set on the transport truck using a jack and slide system. The cargo was jacked and slid back to the foundation from which it had been removed months before.

